

-----Radio Update File Revision History-----

Version 1.005 – November 13, 2013 – 539v1b005.ruf

- Modified pseudo AGC attack so that it is more resistant to loading upon impulse noise
- Corrected occasional startup problem that caused the frequency to jump up or down by 1 step. (very rarely happened, but put in same change from the 599 to help ensure it doesn't)

Version 1.003 – May 3, 2013 – 539v1b003.ruf

- Improved frequency accuracy to help eliminate frequency walk in digital modes using extremely narrow bandwidths
- Added “Manual TUNE” feature

Version 1.000 – Initial Production version – 539v1b000.ruf